


Appendix D - Photos



Current tie back




Existing cable anchor



Existing post shear failure at toe



Rotted post



Totem North wall



Totem South wall