



Photo 1: North from boat launch - Landscaped lawns behind retaining wall – the elevated pier will egress from this corner.



Photo 2: Looking north from Club Mara







Photo 3: Club Mara Marina Site looking south



Photo 4: Dense Milfoil infestation in and around the Club Mara marina

n:\active\2010\1492 bcio biology\10-1492-0096 club mara resort eia\reports\wp\management plan - club mara boat moorage dec 21-10.docx

