



Photo 1.
Looking out at damaged dock to
be replaced.
May 3/13



Photo 2.
Substrate grading from small
gravel to cobble.
May 3/13



Photo 3.
Substrate grading from small
gravel to cobble.
May 3/13



Photo 4.

Looking south from proposed dock location showing existing shoreline development.

May 3/13



Photo 5.

Looking north from proposed dock location, showing existing shoreline development.

May 3/13



Photo 6.

Looking toward shore at existing dock, showing shoreline vegetation.

May 3/13