

Management Plan and Background

Client has been in discussions with Compliance and Enforcement for the past few seasons. This application was in response to a trespass notice which required applicant to apply for a Crown Land Tenure. The following are some notes:

- The applicant has been working with Surveyor General to help determine the property line. Client believes that natural boundary shown on old plans is out in the lake below what the Crown considers the Present Natural Boundary.
- Applicant has 15 buoys and client wants that to be part of tenure.
- Fuel on upland is double walled tank and built to current standards relatively recently.
- No sewage pump out.
- Extensive fill and rework of the entire area over time. See notes and pictures on file.